

CenterLine (Windsor) Limited Tel: 519-734-8464, Email: info@cntrline.com, www.cntrline.com



For your specific


configuration, consult the VeriFast™ User

Manual, available at

## Pneumatic Connection Diagram for LVDT Weld Bodies with NON-RETRACTABLE PINS

## This information does not apply to:

- VeriFast LVDT Clamp Mount Weld Bodies
- · Ring weld or clinching applications



Protected by U.S. patents; other U.S. and foreign patents pending.

CenterLine (Windsor) Limited Tel: 519-734-8464, Email: info@cntrline.com, www.cntrline.com FDP-VFA-LVD-OI-QS-PR-1.0-0517